

General Information

Date & Time: 23, Jul, 2026 12:13

Make	Mitsubishi	Model	L300
YOM	2026	Odo Meter Reading	13,841
Registration No.	NLD8175	Chassis No.	PAEL65NYTSB014273
CC	2.2	Transmission	M/T
Fuel Type	Diesel	Type of Body	FB Body
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	74.0	76	77	69
2	Boot Lid	79.8	69	88	83
3	Roof	79.2	69	104	72/72
4	Left Front Fender	74.0	70	76	76
5	Left Front Door	70.3	70	66	75
6	Center Panel Left	82.4	85	84	78
7	Left Rear Door				
8	Left Back Panel	93.8	89	108	84
9	Right Front Fender	71.1	67	71	76
10	Right Front Door	68.9	71	69	67
11	Center Panel Right	79.7	80	82	77
12	Right Rear Door				
13	Right Back Panel	92.3	75	104	98

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Worked - Small / Ceiling - Grime - Minimal	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch & Dent - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Side Gate - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch - Minimal / Cargo Bed Floor - Scratch - Medium / Rear Gate - Scratch - Minimal / Roof - Scratch - Large / (L) Center Panel - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Minimal / Front Panel - Scratch & Dent - Minimal / Front Windshield - Scratch, Stone chip - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
With Lto plate, with spare tire and jack, with warranty booklet, 1key, no tools,