


General Information

Date & Time: 24, Jul, 2026 15:41

Make	Toyota	Model	Avanza
YOM	2025	Odo Meter Reading	29,927
Registration No.	DBT2435	Chassis No.	MHFAB1BY4R3132931
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	MPV
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	116.0	118	116	114
2	Boot Lid	114.0	107	113	122
3	Roof	116.2	126	121	108/110
4	Left Front Fender	104.3	107	103	103
5	Left Front Door	126.6	122	123	135
6	Center Panel Left				
7	Left Rear Door	123.6	126	115	130
8	Left Back Panel	127.0	136	121	124
9	Right Front Fender	109.0	109	113	105
10	Right Front Door	119.6	127	119	113
11	Center Panel Right				
12	Right Rear Door	117.0	121	109	121
13	Right Back Panel	119.3	117	113	128

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Medium / Rear Seat - Grime - Large / Dashboard - Worn, Scratch, Cut, Crack - Minimal / (L) Front Floor Mat - Cut, Crack - Small / (R) Front Floor Mat - Grime - Minimal / (L) Front Trim - Worked - Small / (R) Front Trim - Worked - Small / Ceiling - Grime - Small	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Dent - Large / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Crack, Gap - Medium / Bonnet, Headlight - Scratch & Dent - Small / Roof - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with Ito plate/with warranty booklet/with spare tire/with spare remote key/with dent and hairlines scratches on the body/with reverse camera/with tools and jack