

General Information

Date & Time: 24, Jul, 2026 15:44

Make	Toyota	Model	Avanza
YOM	2025	Odo Meter Reading	44,139
Registration No.	NJA2085	Chassis No.	MHFAB1BY4R3126210
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	MPV
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	112.0	107	113	116
2	Boot Lid	106.6	105	110	105
3	Roof	117.7	125	123	111/112
4	Left Front Fender	99.5	95	102	102
5	Left Front Door	117.3	105	123	124
6	Center Panel Left				
7	Left Rear Door	119.0	122	113	122
8	Left Back Panel	115.0	124	115	106
9	Right Front Fender	105.1	109	107	100
10	Right Front Door	118.0	124	118	112
11	Center Panel Right				
12	Right Rear Door	117.3	121	115	116
13	Right Back Panel	112.0	105	109	122

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Small / (R) Front Floor Mat - Grime - Small / (L) Front Floor Mat - Worked - Small / (L) Front Seat - Worn - Yes / Dashboard - Traces of Adhesive Tape - Yes / Ceiling - Grime - Minimal / (R) Front Seat - Grime - Small	Remarks (L) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / (R) Rear Fender, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Fender, Molding - Crack, Gap - Small / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch & Dent - Large / Roof - Rust, Corrosion - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

with LTO plate/with warranty booklet/with incomplete tools with jack/no spare tire/no spare key/with seat cover/hairline scratches on the body