

General Information

Date & Time: 03, Mar, 2025 18:35

Make	Toyota	Model	Vios
YOM	2024	Mileage	21,649
Registration No.	NEY4901	Chassis No.	PA1B18F32R4255779
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.3	113	103	106
2	Boot Lid	99.4	91	105	102
3	Roof	94.7	100	90	93/96
4	Left Front Fender	92.3	96	91	91
5	Left Front Door	94.4	91	92	100
6	Center Panel Left				
7	Left Rear Door	99.5	109	97	93
8	Left Back Panel	106.0	107	107	104
9	Right Front Fender	91.3	91	92	91
10	Right Front Door	87.3	87	86	89
11	Center Panel Right				
12	Right Rear Door	98.4	86	96	114
13	Right Back Panel	102.9	103	94	112

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Seat - Grime - Medium / Rear Seat - Grime - Small / (R) Front Seat - Grime - Medium / (L) Front Floor Mat - Worked - Small	Remarks Bonnet, Headlight - Scratch - Medium / (R) Front Fender, Molding - Dent - Medium / Front Bumper, Grille, Lamps - Scratch - Medium / (L) Front Fender, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch - Large / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Repair mark - Difference in Color / (L) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / (R) Rear Fender, Molding - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch - Large / Roof - Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with warranty booklet and LTO plate/ with spare tire and jack/ with tools/ abnormal noise on rear brakes/