

General Information

Date & Time: 25, Jul, 2026 15:06

Make	Toyota	Model	Hilux Tamaraw
YOM	2025	Odo Meter Reading	11,792
Registration No.	EAH6009	Chassis No.	PAHACACA7S6428143
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Utility Passenger
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.8	112	103	94
2	Boot Lid	52.7	48	53	57
3	Roof	112.7	123	109	108/111
4	Left Front Fender	111.3	105	113	116
5	Left Front Door	100.3	100	100	101
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	56.0	55	54	60
9	Right Front Fender	114.6	121	118	105
10	Right Front Door	105.6	102	106	109
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	62.3	59	65	63

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Dash-board - Traces of Adhesive Tape - Yes / (L) Front Floor Mat - Worked - Small / (R) Front Floor Mat - Worked - Small / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / (L) Front Trim - Worked - Small / (R) Front Trim - Worked - Small / Ceiling - Grime - Medium / Overall Interior - Smell - Yes	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Side Gate - Scratch - Large / Rear Gate - Scratch - Minimal / Cargo Bed Floor - Scratch & Dent - Large / (L) Side Gate - Scratch - Small / (L) Front Door, Molding - Scratch - Small / Roof - Dent - Medium / (L) Front Fender, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Large / Bonnet, Headlight - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes

with Ito plate/with warranty booklet/with spare tire/with spare key/with dent and scratches on the body/with tools and jack/without reverse camera