


General Information

Date & Time: 04, Mar, 2025 13:37

Make	Toyota	Model	Vios
YOM	2024	Mileage	11,415
Registration No.	NEY5639	Chassis No.	PA1B18F30R4260818
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	113.3	118	111	111
2	Boot Lid	111.3	108	110	116
3	Roof	101.6	107	101	102/97
4	Left Front Fender	94.8	96	95	94
5	Left Front Door	94.2	96	93	94
6	Center Panel Left				
7	Left Rear Door	104.3	109	104	100
8	Left Back Panel	103.3	103	105	102
9	Right Front Fender	97.8	102	96	95
10	Right Front Door	99.5	102	100	97
11	Center Panel Right				
12	Right Rear Door	112.0	104	109	123
13	Right Back Panel	97.0	97	97	97

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Medium / Rear Seat - Grime - Small	Remarks (L) Mirror - Scratch - Small / (R) Rear Door, Molding - Dent - Small / (R) Front Fender, Molding - Dent - Medium / Front Bumper, Grille, Lamps - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with warranty booklet, spare tire, jack and tools. with LTO plate.