

General Information

Date & Time: 27, Jul, 2026 08:36

Make	Toyota	Model	Innova
YOM	2025	Odo Meter Reading	91,333
Registration No.	NHS3093	Chassis No.	PA2JA8EM8R0144436
CC	2.8	Transmission	A/T
Fuel Type	Diesel	Type of Body	Wagon
Colour	Red Mica Metallic		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	113.6	115	126	100
2	Boot Lid	115.3	118	119	109
3	Roof	98.9	114	91	96/95
4	Left Front Fender	268.0	145	161	498
5	Left Front Door	365.0	765	182	148
6	Center Panel Left				
7	Left Rear Door	106.3	108	105	106
8	Left Back Panel	119.0	125	120	112
9	Right Front Fender	103.9	99	104	109
10	Right Front Door	110.0	112	112	106
11	Center Panel Right				
12	Right Rear Door	105.8	100	110	108
13	Right Back Panel	119.3	116	113	129

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Seat - Worn - Yes / (L) Front Floor Mat - Worked - Small / (R) Front Trim - Grime - Medium / (L) Front Trim - Grime - Medium / Ceiling - Grime - Medium / (R) Rear Trim - Grime - Minimal / (L) Rear Trim - Grime - Minimal / (R) Front Seat - Grime - Small / Dashboard - Traces of Adhesive Tape - Yes / Glove Box - Worn, Scratch, Cut, Crack - Small / Rear Seat - Grime - Minimal	Remarks (L) Front Fender - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / Roof - Scratch - Medium / (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Repair mark - Yes / (R) Rear Door, Molding - Repair mark - Yes / (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Front Door, Molding - Repair mark - Yes / (L) Front Fender, Molding - Repair mark - Yes / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Bonnet, Headlight - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes

with warranty booklet, jack and tools, with spare tire, with one LTO plate and one modified plate, scratches on tail light, driver's door issue