

General Information

Date & Time: 28, Jul, 2026 15:32

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	51,733
Registration No.	NJC8543	Chassis No.	PA1B18F35S4291682
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	111.0	128	101	104
2	Boot Lid	108.3	110	106	109
3	Roof	101.4	108	101	100/97
4	Left Front Fender	101.8	102	97	107
5	Left Front Door	105.3	103	105	108
6	Center Panel Left				
7	Left Rear Door	101.4	108	98	98
8	Left Back Panel	111.2	117	119	98
9	Right Front Fender	103.2	108	96	106
10	Right Front Door	107.9	117	100	107
11	Center Panel Right				
12	Right Rear Door	108.5	97	111	118
13	Right Back Panel	106.6	104	107	109

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Trim - Grime - Small / (R) Front Trim - Grime - Small / (L) Front Floor Mat - Worked - Small / (R) Front Floor Mat - Grime - Minimal / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / Mat Other - Worked - Small / Rear Seat - Grime - Small / Ceiling - Grime - Medium / Dashboard - Worn, Scratch, Cut, Crack - Minimal	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Large / Bonnet, Headlight - Scratch - Minimal / Roof - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with Ito plate/with warranty booklet/with spare key/with spare tire/with tools and jack/with dent and scratches on the body/with reverse camera