

General Information

Date & Time: 24, Jul, 2026 15:45

Make	Toyota	Model	Vios
YOM	2026	Odo Meter Reading	4,669
Registration No.	VAC6108	Chassis No.	PA1B18F3XS4306435
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	117.6	122	119	112
2	Boot Lid	107.0	108	104	109
3	Roof	107.0	109	112	100/107
4	Left Front Fender	119.0	125	108	124
5	Left Front Door	121.3	119	123	122
6	Center Panel Left				
7	Left Rear Door	120.6	129	123	110
8	Left Back Panel	119.6	124	118	117
9	Right Front Fender	108.3	111	105	109
10	Right Front Door	114.3	121	107	115
11	Center Panel Right				
12	Right Rear Door	109.6	104	108	117
13	Right Back Panel	121.0	122	118	123

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A		Exterior Evaluation : B	
			
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain		A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap	
Remarks Rear Seat - Grime - Small / (R) Front Trim - Grime - Minimal / (R) Front Floor Mat - Grime - Minimal / (L) Front Trim - Grime - Small / (R) Front Seat - Grime - Minimal / (L) Front Seat - Grime - Minimal / (L) Front Floor Mat - Grime - Minimal		Remarks (L) Front Fender, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / Roof - Scratch - Small	
Frame Evaluation : A		Functional Evaluation : A	
Remarks Defects not found		Remarks Spare Key - Issue - Unexist	

Inspector Notes

with LTO plate/with warranty booklet/no tools and jack/with spare tire/no spare key/stitch marks on seats/hairline scratches on the body