

General Information

Date & Time: 23, Jul, 2026 08:04

Make	Mitsubishi	Model	L300
YOM	2026	Odo Meter Reading	8,041
Registration No.	NLB1996	Chassis No.	PAEL65NYTSB010739
CC	2.2	Transmission	M/T
Fuel Type	Diesel	Type of Body	FB Body
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	87.6	86	92	85
2	Boot Lid	88.3	101	83	82
3	Roof	76.1	78	77	76/74
4	Left Front Fender	98.9	79	85	133
5	Left Front Door	75.8	75	72	80
6	Center Panel Left	85.7	91	86	81
7	Left Rear Door				
8	Left Back Panel	108.6	91	104	131
9	Right Front Fender	81.9	78	88	79
10	Right Front Door	76.5	80	71	78
11	Center Panel Right	85.6	82	92	83
12	Right Rear Door				
13	Right Back Panel	106.4	81	101	137

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Floor Mat - Grime - Small / Ceiling - Grime - Minimal / (L) Front Trim - Grime - Small / Carpet - Worked - Minimal	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch & Dent - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Side Gate - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch - Small / Rear Gate - Scratch & Dent - Minimal / Cab Back Panel - Modified - Large / (L) Side Gate - Scratch & Dent - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Repair mark - Difference in Color / (L) Front Fender, Molding - Scratch - Minimal / Front Panel - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Cargo Bed Floor - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

With Lto plate, with spare tire and warranty booklet, 1key, no jack and tools,