

General Information

Date & Time: 03, Mar, 2025 13:01

Make	Toyota	Model	Hilux
YOM	2022	Mileage	53,678
Registration No.	CBD2695	Chassis No.	MR0JB8DDSN3193403
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Pickup
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	123.0	123	127	119
2	Boot Lid	105.6	108	108	101
3	Roof	108.0	92	103	116/121
4	Left Front Fender	107.6	101	111	111
5	Left Front Door	94.4	95	97	91
6	Center Panel Left				
7	Left Rear Door	91.2	94	93	87
8	Left Back Panel	96.0	94	88	106
9	Right Front Fender	102.0	100	103	103
10	Right Front Door	92.8	94	95	90
11	Center Panel Right				
12	Right Rear Door	94.1	89	93	101
13	Right Back Panel	103.5	114	96	101

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : D	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Medium / (L) Front Seat - Grime - Small / Rear Seat - Grime - Large / (L) Front Floor Mat - Cut, Crack - Small / (R) Front Trim - Grime - Large / (R) Rear Trim - Grime - Medium / (L) Front Trim - Grime - Medium / (L) Rear Trim - Grime - Medium	Remarks Front Bumper, Grille, Lamps - Scratch & Dent - Large / Roof - Scratch - Large / (R) Side Gate - Scratch & Dent - Large / (R) Front Door, Molding - Scratch & Dent - Small / (L) Side Gate - Scratch - Large / Rear Gate - Dent - Small / Bonnet, Headlight - Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with spare tire and LTO plate/ no tools and warranty booklet/ no jack/