

General Information

Date & Time: 22, Jul, 2026 15:52

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	18,513
Registration No.	NHS3566	Chassis No.	PA1B18F39R4254810
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.0	99	111	97
2	Boot Lid	112.0	105	109	122
3	Roof	97.7	101	97	93/100
4	Left Front Fender	100.3	100	97	104
5	Left Front Door	105.0	109	103	103
6	Center Panel Left				
7	Left Rear Door	109.9	121	110	99
8	Left Back Panel	108.3	113	105	107
9	Right Front Fender	105.6	105	103	109
10	Right Front Door	101.3	106	102	96
11	Center Panel Right				
12	Right Rear Door	109.0	104	102	121
13	Right Back Panel	115.3	112	105	129

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Minimal / Rear Seat - Grime - Small / (R) Front Trim - Grime - Small / (R) Front Floor Mat - Grime - Small / (L) Front Trim - Grime - Small / (L) Front Seat - Worn - Yes / (L) Front Floor Mat - Cut, Crack - Small	Remarks Front Bumper, Grille, Lamps - Scratch - Large / (L) Rear Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / (L) Front Door, Molding - Scratch & Dent - Medium / (L) Front Fender, Molding - Scratch - Small / Roof - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes

with LTO plate/with warranty booklet/with incomplete tools with jack/with spare tire/with spare key/with seat cover/hairline scratches on the body