

General Information

Date & Time: 22, Jul, 2026 15:58

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	13,452
Registration No.	NHS9338	Chassis No.	PA1B18F31R4268328
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	123.3	124	116	130
2	Boot Lid	128.6	130	122	134
3	Roof	118.2	132	114	111/116
4	Left Front Fender	115.6	114	116	117
5	Left Front Door	127.0	137	121	123
6	Center Panel Left				
7	Left Rear Door	120.6	121	117	124
8	Left Back Panel	126.0	128	129	121
9	Right Front Fender	127.3	121	124	137
10	Right Front Door	130.0	123	132	135
11	Center Panel Right				
12	Right Rear Door	125.3	125	125	126
13	Right Back Panel	126.3	124	122	133

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Small / (L) Front Trim - Grime - Minimal / (R) Front Trim - Grime - Minimal / Ceiling - Grime - Small / (L) Front Seat - Grime - Minimal / Rear Seat - Grime - Minimal	Remarks Roof - Scratch - Small / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch - Small / (R) Rear Fender, Molding - Scratch & Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Rear Door, Molding - Scratch & Dent - Minimal / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Minimal / (R) Front Fender, Molding - Scratch & Dent - Minimal / Bonnet, Headlight - Scratch & Dent - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / (L) Front Fender, Molding - Scratch & Dent - Minimal / (L) Front Door, Molding - Scratch & Dent - Minimal / (R) Front Door, Molding - Scratch & Dent - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with LTO plate, with spare tire, with reverse camera, with jack and inc tools, with manual booklet, no warranty, no spare key, scratches and dent on exterior, scratches in taillight and headlight, issue in trunk latch.