

General Information

Date & Time: 24, Jul, 2026 16:03

Make	Toyota	Model	Hilux Tamaraw
YOM	2025	Odo Meter Reading	26,993
Registration No.	NKU3136	Chassis No.	PAHACACA6S6426481
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Utility Passenger
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	105.0	110	108	97
2	Boot Lid	52.2	60	48	48
3	Roof	113.2	122	112	114/105
4	Left Front Fender	101.5	106	96	103
5	Left Front Door	100.3	102	97	102
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	69.7	56	90	64
9	Right Front Fender	101.6	107	106	92
10	Right Front Door	104.3	103	108	102
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	64.4	59	70	64

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Loose, Deformed - Medium / (L) Front Floor Mat - Worked - Small / Console, Switches, Vents - Loose, Deformed - Medium / Carpet - Worked - Minimal	Remarks (R) Front Fender, Molding - Scratch - Medium / (R) Mirror - Crack - Damaged / (R) Front Door, Molding - Scratch - Medium / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Side Gate - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / Cargo Bed Floor - Scratch - Large / Roof - Scratch & Dent - Small / (L) Side Gate - Scratch - Large / (L) Front Door, Molding - Scratch & Dent - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Crack, Gap - Large / Bonnet, Headlight - Scratch - Large / (L) Step, In-panel, Side Spoiler - Scratch - Small / Rear Gate - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
With Lto plate, with spare tire and warranty booklet, 1key, no tools and Jack, Crack taillight, shifting knob partially missing