

## General Information

Date & Time: 22, Jul, 2026 15:39

|                  |         |                   |                   |
|------------------|---------|-------------------|-------------------|
| Make             | Toyota  | Model             | Vios              |
| YOM              | 2024    | Odo Meter Reading | 59,521            |
| Registration No. | NFR8868 | Chassis No.       | PA1B18F38R4258024 |
| CC               | 1.3     | Transmission      | CVT               |
| Fuel Type        | Gas     | Type of Body      | Sedan             |
| Colour           | Blue    |                   |                   |

## Body / Panel Condition





| #  | Area               | Thickness(um) |        |        |          |
|----|--------------------|---------------|--------|--------|----------|
|    |                    | Average       | Value1 | Value2 | Value3/4 |
| 1  | Bonnet             | 112.3         | 125    | 105    | 107      |
| 2  | Boot Lid           | 113.3         | 112    | 106    | 122      |
| 3  | Roof               | 101.0         | 103    | 100    | 101/100  |
| 4  | Left Front Fender  | 104.6         | 105    | 102    | 107      |
| 5  | Left Front Door    | 109.3         | 107    | 111    | 110      |
| 6  | Center Panel Left  |               |        |        |          |
| 7  | Left Rear Door     | 105.6         | 107    | 108    | 102      |
| 8  | Left Back Panel    | 115.3         | 127    | 111    | 108      |
| 9  | Right Front Fender | 112.3         | 118    | 112    | 107      |
| 10 | Right Front Door   | 109.6         | 105    | 111    | 113      |
| 11 | Center Panel Right |               |        |        |          |
| 12 | Right Rear Door    | 111.0         | 107    | 114    | 112      |
| 13 | Right Back Panel   | 113.6         | 105    | 109    | 127      |

## Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

| Interior Evaluation : <span style="color: red;">C</span>                                                                                                                                                                                                                                                                               | Exterior Evaluation : <span style="color: red;">C</span>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
|  <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>                                                                                     |  <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>                                                                                                                                                                                                                                                                                                                                                                                                                                  |
| <p><b>Remarks</b><br/>(L) Front Floor Mat - Cut, Crack - Medium / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Medium / Rear Seat - Grime - Medium / (R) Front Floor Mat - Worked - Small / (L) Front Trim - Grime - Medium / (R) Front Trim - Grime - Small / Ceiling - Grime - Medium / Mat Other - Grime - Minimal</p> | <p><b>Remarks</b><br/>(R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Dent - Small / Rear Bumper, Lamps, Panels - Dent - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Small / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Large / Bonnet, Headlight - Scratch &amp; Dent - Medium / Roof - Scratch - Minimal / Member (Bolted) - Dent - Yes</p> |
| Frame Evaluation : <span style="color: red;">A</span>                                                                                                                                                                                                                                                                                  | Functional Evaluation : <span style="color: red;">A</span>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |
| <p><b>Remarks</b><br/>Defects not found</p>                                                                                                                                                                                                                                                                                            | <p><b>Remarks</b><br/>Defects not found</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |

| Inspector Notes                                                                                                                                                |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------|
| with Ito plate/without warranty booklet/with 2 spare key/with tools and jack/with spare tire/with reverse camera/with dent and hairlines scratches on the body |