

General Information

Date & Time: 25, Jul, 2026 15:31

Make	Toyota	Model	Wigo
YOM	2026	Odo Meter Reading	18,858
Registration No.	NJK6094	Chassis No.	MHKAA1BC8SJ048301
CC	1.0	Transmission	CVT
Fuel Type	Gas	Type of Body	Hatchback
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	126.0	133	122	123
2	Boot Lid	113.6	104	122	115
3	Roof	103.2	102	102	107/102
4	Left Front Fender	105.6	116	98	103
5	Left Front Door	111.3	119	109	106
6	Center Panel Left				
7	Left Rear Door	109.3	114	107	107
8	Left Back Panel	106.1	96	111	111
9	Right Front Fender	111.0	108	104	121
10	Right Front Door	116.3	117	118	114
11	Center Panel Right				
12	Right Rear Door	111.0	110	110	113
13	Right Back Panel	105.5	103	117	97

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Dashboard - Traces of Adhesive Tape - Yes / (L) Front Floor Mat - Grime - Minimal / (R) Front Floor Mat - Grime - Minimal / Console, Switches, Vents - Worn, Scratch, Cut, Crack - Minimal / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Minimal / Rear Seat - Grime - Small / (L) Front Trim - Worked - Small / (R) Front Trim - Worked - Small / Ceiling - Grime - Minimal / Mat Other - Worked - Small	Remarks (R) Front Fender, Molding - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch - Large / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch & Dent - Large / (L) Rear Door, Molding - Scratch - Large / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Crack, Gap - Medium / Bonnet, Headlight - Dent - Large / Member (Bolted) - Dent - Yes / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Roof - Scratch - Small / Antennae - Damaged - Yes
Frame Evaluation : B	Functional Evaluation : A
Remarks Front Cross Member Support - Traces of Bending, or Marks of Panel Repair ? - Yes	Remarks Defects not found

Inspector Notes
with Ito plate/with warranty booklet/with spare tire/with spare key/with dent and scratches on the body/without tools and jack/maintenance warning lamp on