

General Information

Date & Time: 03, Mar, 2025 14:20

Make	Toyota	Model	Avanza
YOM	2022	Mileage	69,289
Registration No.	DAQ6985	Chassis No.	MHFAA1BY2N0004038
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	MPV
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	181.3	197	165	182
2	Boot Lid	174.3	179	203	141
3	Roof	200.7	223	195	178/207
4	Left Front Fender	166.0	166	162	170
5	Left Front Door	170.6	155	165	192
6	Center Panel Left				
7	Left Rear Door	174.3	192	160	171
8	Left Back Panel	180.6	178	158	206
9	Right Front Fender	182.0	162	172	212
10	Right Front Door	154.6	155	144	165
11	Center Panel Right				
12	Right Rear Door	162.3	175	146	166
13	Right Back Panel	181.3	202	160	182

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Medium / (R) Front Seat - Grime - Small / Ceiling - Grime - Small	Remarks (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / Roof - Repair Traces - Yes / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Dent - Minimal / (L) Mirror - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Roof - Scratch - Small
Frame Evaluation : A	Functional Evaluation : D
Remarks Defects not found	Remarks Panel, Meter - Issue - Yes / Power Steering - Issue - Yes / Battery - Weak - Yes / Spare Key - Issue - Unexist

Inspector Notes
with warranty booklet, no jack, no tools, with spare tire, with LTO plate, dead battery, power steering issue due to dead battery