

General Information

Date & Time: 24, Jul, 2026 11:12

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	23,169
Registration No.	CCR3054	Chassis No.	PA1B18F34S4292192
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	115.0	115	109	121
2	Boot Lid	113.0	108	104	127
3	Roof	106.5	110	105	101/110
4	Left Front Fender	113.0	119	103	117
5	Left Front Door	86.5	80	78	101
6	Center Panel Left				
7	Left Rear Door	108.6	113	111	102
8	Left Back Panel	107.0	110	107	104
9	Right Front Fender	117.3	117	122	113
10	Right Front Door	114.3	111	113	119
11	Center Panel Right				
12	Right Rear Door	105.7	111	107	99
13	Right Back Panel	105.4	88	108	120

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Minimal / Rear Seat - Grime - Medium / (R) Front Trim - Grime - Minimal / (L) Front Trim - Grime - Minimal	Remarks (L) Front Fender - Repair Traces - Yes / (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Rear Door, Molding - Scratch & Dent - Small / Rear Windshield - Damaged - Large / Trunk Hood, Rear Gate - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Crack, Gap - Large / (R) Rear Fender, Molding - Scratch & Dent - Large / (L) Rear Fender, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Repair mark - Yes / (L) Front Door, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Front Fender, Molding - Scratch & Dent - Minimal / Roof - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Large / Bonnet, Headlight - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
With Lto plate, with jack, 1key, NO warranty booklet and spare tire and tools ,scratches on headlights, Crack taillight ,