

General Information

Date & Time: 03, Mar, 2025 15:33

Make	Suzuki	Model	Dzire
YOM	2024	Mileage	1,112
Registration No.	NKD2872	Chassis No.	MBHZF63S0SG524579
CC	1.2	Transmission	A/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.3	107	105	110
2	Boot Lid	90.9	95	89	89
3	Roof	112.5	104	105	119/122
4	Left Front Fender	100.0	100	103	97
5	Left Front Door	108.6	113	105	108
6	Center Panel Left				
7	Left Rear Door	102.8	109	103	97
8	Left Back Panel	103.2	114	107	89
9	Right Front Fender	102.8	101	108	100
10	Right Front Door	106.3	105	104	110
11	Center Panel Right				
12	Right Rear Door	106.3	106	108	105
13	Right Back Panel	103.3	92	107	111

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks Front Bumper, Grille, Lamps - Scratch - Small / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
with warranty booklet/ with spare tire and jack / incomplete tools/ with LTO plate