

General Information

Date & Time: 29, Jul, 2026 05:28

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	54,057
Registration No.	FAS4076	Chassis No.	PA1B18F38R4277365
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	98.5	96	101	98
2	Boot Lid	108.4	99	107	119
3	Roof	86.9	98	84	86/79
4	Left Front Fender	92.4	92	93	92
5	Left Front Door	96.3	98	97	94
6	Center Panel Left				
7	Left Rear Door	99.4	99	98	101
8	Left Back Panel	101.1	102	97	104
9	Right Front Fender	91.4	91	92	91
10	Right Front Door	93.6	95	95	91
11	Center Panel Right				
12	Right Rear Door	92.9	96	89	94
13	Right Back Panel	97.2	94	93	105

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Large / Rear Seat - Grime - Large / (L) Front Trim - Grime - Minimal / (R) Front Seat - Grime - Medium / Carpet - Worked - Minimal / Console, Switchs, Vents - Worked - Minimal	Remarks (R) Front Fender, Molding - Scratch & Dent - Large / (R) Front Door, Molding - Scratch - Large / (R) Rear Door, Molding - Scratch - Large / (R) Rear Fender, Molding - Dent - Large / Rear Bumper, Lamps, Panels - Scratch - Large / Trunk Hood, Rear Gate - Scratch - Large / (L) Rear Fender, Molding - Crack, Gap - Small / (L) Rear Door, Molding - Scratch - Minimal / (L) Mirror - Scratch, Peeled - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Bonnet, Headlight - Scratch & Dent - Large / Roof - Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
with lto plates, no warranty booklet, with spare tire, no jack, inc tools, front lto plate issue, with hairline scratches