

General Information

Date & Time: 28, Jul, 2026 17:50

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	53,554
Registration No.	FAS3569	Chassis No.	PA1B18F35R4277095
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	85.7	85	85	87
2	Boot Lid	93.2	93	88	99
3	Roof	76.2	73	87	69/77
4	Left Front Fender	91.0	100	85	88
5	Left Front Door	84.9	86	85	85
6	Center Panel Left				
7	Left Rear Door	97.8	96	103	95
8	Left Back Panel	103.0	104	103	102
9	Right Front Fender	88.8	84	93	90
10	Right Front Door	84.3	92	81	80
11	Center Panel Right				
12	Right Rear Door	87.8	84	86	94
13	Right Back Panel	93.3	95	90	96

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Large / Overall Interior - Animal Hair - Yes	Remarks (R) Front Fender, Molding - Crack, Gap - Large / (R) Front Door, Molding - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (L) Rear Door, Molding - Modified - Medium / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Crack, Gap - Large / Front Bumper, Grille, Lamps - Scratch & Dent - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes

with lto plates, no warranty bookelet, with spare tire, no jack, ni tools, issue on right tail light, with hairline scratches in the body