

General Information

Date & Time: 29, Jul, 2026 13:29

Make	Suzuki	Model	Jimny
YOM	2024	Odo Meter Reading	42
Registration No.	DCG7788	Chassis No.	MA3JC74W1R0155072
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Wagon
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	117.3	120	113	119
2	Boot Lid	128.6	137	127	122
3	Roof	122.7	122	113	135/121
4	Left Front Fender	130.6	123	132	137
5	Left Front Door	129.3	132	127	129
6	Center Panel Left				
7	Left Rear Door	127.6	127	128	128
8	Left Back Panel	141.6	152	133	140
9	Right Front Fender	131.0	136	126	131
10	Right Front Door	128.0	124	133	127
11	Center Panel Right				
12	Right Rear Door	133.3	137	131	132
13	Right Back Panel	133.6	135	113	153

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks (R) Front Door, Molding - Scratch & Dent - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Roof - Scratch & Dent - Minimal / (L) Front Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch & Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with LTO plate, with warranty and manual booklet, with reverse camera, with spare tire and key, minor scratches and dent on exterior, scratches in taillight and headlight, engine bay unusual noise when ac is on.