

General Information

Date & Time: 28, Jul, 2026 16:34

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	76,209
Registration No.	GAP5199	Chassis No.	PA1B18F35N4199881
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blackish Red Mica		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	123.3	123	112	135
2	Boot Lid	108.6	108	106	112
3	Roof	107.5	106	109	106/109
4	Left Front Fender	111.6	114	113	108
5	Left Front Door	122.3	125	124	118
6	Center Panel Left				
7	Left Rear Door	110.3	113	109	109
8	Left Back Panel	120.3	131	117	113
9	Right Front Fender	107.3	113	101	108
10	Right Front Door	114.0	124	109	109
11	Center Panel Right				
12	Right Rear Door	107.3	107	105	110
13	Right Back Panel	110.0	115	109	106

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Small / (L) Rear Trim - Grime - Small / (R) Rear Trim - Grime - Minimal / Mat Other - Grime - Small / (R) Front Seat - Grime - Small / (R) Front Floor Mat - Grime - Medium / (R) Front Trim - Grime - Medium / (L) Front Trim - Grime - Medium / (L) Front Seat - Grime - Small / Overall Interior - Smell - Yes / Overall Interior - Animal Hair - Yes / Ceiling - Grime - Small / (L) Front Floor Mat - Grime - Medium	Remarks Front Bumper, Grille, Lamps - Crack, Gap - Large / Bonnet, Headlight - Scratch & Dent - Medium / (R) Front Fender, Molding - Scratch & Dent - Large / (R) Front Door, Molding - Scratch - Large / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch - Large / (R) Rear Fender, Molding - Scratch - Medium / (R) Mirror - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Large / (L) Front Door, Molding - Scratch - Large / (L) Mirror - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Medium / (L) Front Fender, Molding - Dent - Medium
Frame Evaluation : A	Functional Evaluation : E
Remarks Defects not found	Remarks Retractable Mirror - Issue - Yes / Door Lock - Issue - Yes / Power Steering - Issue - Yes / Air Conditioner - Function - Weak / Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
No AC. Large gap at front bumper. Right side retractable mirror issue. Left rear door lock issue. Scratch at Left rear light. Visible hairline scratches. Incomplete tools. With warranty booklet, seatcover, sparetire, jack, LTO Plate and 1key.