

General Information

Date & Time: 03, Mar, 2025 15:27

Make	Toyota	Model	Vios
YOM	2024	Mileage	12,887
Registration No.	NHR2260	Chassis No.	PA1B18F36P4227433
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition




#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.0	105	93	108
2	Boot Lid	104.0	104	106	102
3	Roof	104.7	106	101	105/107
4	Left Front Fender	95.6	97	95	94
5	Left Front Door	92.8	91	92	96
6	Center Panel Left				
7	Left Rear Door	100.2	103	102	96
8	Left Back Panel	106.6	109	107	104
9	Right Front Fender	92.4	90	93	94
10	Right Front Door	94.7	93	95	97
11	Center Panel Right				
12	Right Rear Door	99.0	95	99	103
13	Right Back Panel	98.4	98	98	99

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Medium / (L) Front Floor Mat - Grime - Small / (L) Front Seat - Grime - Small	Remarks (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
without warranty booklet and tools. with spare tire and jack. with LTO plate. Has dashcam wire at the flooring.