

General Information

Date & Time: 29, Jul, 2026 16:02

Make	Toyota	Model	Avanza
YOM	2018	Odo Meter Reading	80,147
Registration No.	NCV4997	Chassis No.	MHKM5EF2FHK011637
CC	1.3	Transmission	A/T
Fuel Type	Gas	Type of Body	Wagon
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	97.2	105	87	100
2	Boot Lid	96.6	90	103	97
3	Roof	79.9	74	75	88/82
4	Left Front Fender	88.6	96	92	78
5	Left Front Door	93.2	94	98	89
6	Center Panel Left				
7	Left Rear Door	95.8	94	100	94
8	Left Back Panel	85.3	83	88	85
9	Right Front Fender	89.6	81	96	92
10	Right Front Door	94.3	96	100	88
11	Center Panel Right				
12	Right Rear Door	96.3	97	99	94
13	Right Back Panel	94.5	101	91	92

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Floor Mat - Grime - Small / (R) Front Trim - Grime - Small / (R) Rear Trim - Grime - Minimal / Rear Seat - Grime - Small / (R) Front Seat - Grime - Minimal / (L) Rear Trim - Grime - Small / (L) Front Trim - Grime - Medium / (L) Front Seat - Grime - Minimal / Overall Interior - Smell - Yes	Remarks (L) Front Fender, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Medium / (R) Mirror - Scratch - Minimal / (R) Front Fender, Molding - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch - Large / Bonnet, Headlight - Scratch - Small / Roof - Scratch - Small / Overall Exterior - Faded(Color, Gloss) - Yes
Frame Evaluation : A	Functional Evaluation : C
Remarks Defects not found	Remarks Air Conditioner - Function - Weak / Battery - Weak - Yes / Reverse Camera - N/A - Yes

Inspector Notes
with LTO plate/with warranty booklet/with incomplete tools with jack/with spare tire/with spare key/with seat cover/aircon issue/headlight cover issue/hairline scratches on the body