

General Information

Date & Time: 29, Jul, 2026 15:56

Make	Toyota	Model	Vios
YOM	2021	Odo Meter Reading	146,906
Registration No.	CAW5389	Chassis No.	PA1B18F38M4156201
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	112.0	122	109	105
2	Boot Lid	123.3	118	141	111
3	Roof	93.5	100	94	90/90
4	Left Front Fender	94.6	95	91	98
5	Left Front Door	102.0	106	100	100
6	Center Panel Left				
7	Left Rear Door	104.3	101	99	113
8	Left Back Panel	107.0	108	108	105
9	Right Front Fender	97.1	100	94	97
10	Right Front Door	96.6	91	97	102
11	Center Panel Right				
12	Right Rear Door	100.1	99	98	103
13	Right Back Panel	100.6	101	100	101

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Large / (R) Front Trim - Grime - Medium / (R) Front Seat - Grime - Minimal / Trunk Room - Worn, Scratch, Cut, Crack - Small / (L) Front Trim - Grime - Small / Carpet - Worked - Minimal / (L) Front Floor Mat - Worked - Small / Console, Switches, Vents - Loose, Deformed - Medium	Remarks (R) Front Fender, Molding - Scratch & Dent - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch & Dent - Large / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Rear Door, Molding - Scratch - Large / (R) Rear Fender, Molding - Scratch & Dent - Small / Roof - Scratch & Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch & Dent - Minimal / (L) Rear Fender, Molding - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Rust, Corrosion - Small / (L) Front Door, Molding - Scratch & Dent - Small / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch - Minimal / Roof Spoiler, Molding - Scratch & Dent - Medium
Frame Evaluation : A	Functional Evaluation : C
Remarks Defects not found	Remarks Warning Lamps - Issue - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

No Lto plate, 1key, no warranty booklet and tools, no spare tire and jack, scratches on headlights, check engine warning lamp on, traction control lamp on, maintenance warning lamp on, ABS warning lamp on, airbag warning lamp on, plate light issue