

General Information

Date & Time: 03, Mar, 2025 17:12

Make	Toyota	Model	Vios
YOM	2024	Mileage	29,788
Registration No.	CAZ7958	Chassis No.	PA1B18F31P4236041
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition




#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	160.6	172	149	161
2	Boot Lid	156.6	150	158	162
3	Roof	154.5	169	152	142/155
4	Left Front Fender	140.0	143	137	140
5	Left Front Door	137.0	130	138	143
6	Center Panel Left				
7	Left Rear Door	148.0	148	151	145
8	Left Back Panel	152.6	163	154	141
9	Right Front Fender	147.3	153	140	149
10	Right Front Door	150.3	148	145	158
11	Center Panel Right				
12	Right Rear Door	156.6	149	150	171
13	Right Back Panel	142.3	139	145	143

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Mat Other - Grime - Large / (R) Front Seat - Grime - Large / (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Small / Rear Seat - Grime - Large / Dashboard - Traces of Adhesive Tape - Yes / Ceiling - Grime - Small	Remarks Rear Bumper, Lamps, Panels - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
no warranty booklet, with jack, no tools, with spare tire, with LTO plate