

General Information

Date & Time: 04, Mar, 2025 14:39

Make	Toyota	Model	Vios
YOM	2024	Mileage	13,175
Registration No.	NHM7796	Chassis No.	PA1B18F36R4240119
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	104.3	101	104	108
2	Boot Lid	99.9	94	100	106
3	Roof	90.0	93	94	83/90
4	Left Front Fender	94.3	96	91	96
5	Left Front Door	100.6	96	105	101
6	Center Panel Left				
7	Left Rear Door	97.7	104	97	92
8	Left Back Panel	100.2	112	98	91
9	Right Front Fender	96.8	99	92	100
10	Right Front Door	96.9	94	92	105
11	Center Panel Right				
12	Right Rear Door	95.8	93	89	106
13	Right Back Panel	96.0	93	92	103

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Seat - Worn - Yes / Dashboard - Traces of Adhesive Tape - Yes / Trunk Room - Worn, Scratch, Cut, Crack - Minimal	Remarks Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Large / Trunk Hood, Rear Gate - Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Front Door, Molding - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Minimal / (L) Mirror - Scratch, Peeled - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with LTO plate/with spare tire/with jack and warranty booklets/without tools