

General Information

Date & Time: 31, Jul, 2026 15:10

Make	MG	Model	RX5
YOM	2019	Odo Meter Reading	87,082
Registration No.	NDA9323	Chassis No.	LSJA24U38KS017030
CC	1.5	Transmission	A/T
Fuel Type	Gas	Type of Body	SUV
Colour	Brown		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	134.0	138	122	142
2	Boot Lid	132.0	139	139	118
3	Roof	220.5	233	228	209/212
4	Left Front Fender	112.6	120	115	103
5	Left Front Door	118.6	123	115	118
6	Center Panel Left				
7	Left Rear Door	131.6	129	125	141
8	Left Back Panel	153.6	154	140	167
9	Right Front Fender	187.0	176	186	199
10	Right Front Door	130.6	127	123	142
11	Center Panel Right				
12	Right Rear Door	249.0	418	166	163
13	Right Back Panel	310.3	298	325	308

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Inspector Notes
With Lto plate, with spare tire, 1key, no warranty booklet and tools and Jack, scratches on headlights, rear wiper issue, check engine warning lamp on,traction control lamp on