


General Information

Date & Time: 31, Jul, 2026 15:14

Make	Mitsubishi	Model	Mirage
YOM	2020	Odo Meter Reading	63,951
Registration No.	GAU1365	Chassis No.	PAEA13MJLLA011461
CC	1.2	Transmission	M/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	129.6	150	117	122
2	Boot Lid	113.0	111	113	115
3	Roof	83.6	80	88	81/86
4	Left Front Fender	133.0	155	137	107
5	Left Front Door	147.0	151	148	142
6	Center Panel Left				
7	Left Rear Door	136.0	143	125	140
8	Left Back Panel	146.3	132	166	141
9	Right Front Fender	114.0	113	108	121
10	Right Front Door	117.3	114	116	122
11	Center Panel Right				
12	Right Rear Door	163.3	225	126	139
13	Right Back Panel	130.3	109	118	164

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Overall Interior - Smell - Yes / (R) Front Seat - Grime - Medium / Rear Seat - Grime - Large / Carpet - Worked - Minimal / (L) Front Seat - Grime - Large / Ceiling - Grime - Large / (R) Rear Trim - Cut, Crack - Large	Remarks (R) Rear Door - Repair Traces - Yes / (R) Mirror - Scratch, Peeled - Minimal / (R) Rear Door, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

with lto plates, with warranty booklet, with soate tire and jack, inc tools, PMS warning, with hairline scratches in the body