

General Information

Date & Time: 03, Aug, 2026 18:39

Make	Ford	Model	EcoSport
YOM	2017	Odo Meter Reading	74,436
Registration No.	CAE1764	Chassis No.	MPBSXXMXKHU71940
CC	1.5	Transmission	A/T
Fuel Type	Gas	Type of Body	SUV
Colour	Blue		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	113.3	112	107	121
2	Boot Lid	102.5	99	114	94
3	Roof	101.9	88	100	114/106
4	Left Front Fender	116.6	111	122	117
5	Left Front Door	110.6	112	118	102
6	Center Panel Left				
7	Left Rear Door	103.3	108	113	89
8	Left Back Panel	104.2	89	104	120
9	Right Front Fender	113.6	117	124	100
10	Right Front Door	114.0	115	112	115
11	Center Panel Right				
12	Right Rear Door	102.5	91	100	117
13	Right Back Panel	109.7	120	113	96

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Inspector Notes
With Lto plate, with spare tire, 1key, no warranty booklet and tools and Jack, scratches on headlights,Crack taillight, check engine warning lamp on, airbag warning lamp on, rear door cover missing and door lock issue, aircon issue