

General Information

Date & Time: 04, Mar, 2025 14:56

Make	Toyota	Model	Vios
YOM	2024	Mileage	10,115
Registration No.	VAB8355	Chassis No.	PA1B18F34R4258845
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	101.1	106	92	106
2	Boot Lid	99.6	93	99	107
3	Roof	96.1	93	97	88/107
4	Left Front Fender	94.3	90	96	97
5	Left Front Door	97.7	97	98	98
6	Center Panel Left				
7	Left Rear Door	94.1	99	100	83
8	Left Back Panel	98.0	104	99	91
9	Right Front Fender	92.1	89	96	91
10	Right Front Door	88.6	85	87	95
11	Center Panel Right				
12	Right Rear Door	93.0	91	92	96
13	Right Back Panel	97.6	94	96	103

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Mat Other - Grime - Medium / (R) Front Floor Mat - Grime - Medium / (L) Front Floor Mat - Worked - Small / (L) Front Floor Mat - Grime - Medium / (L) Front Trim - Grime - Minimal	Remarks (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Large / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
with warranty booklet, no jack, incomplete tools, with spare tire, with LTO plate, adhesive mark on trunk hood and headlight