

General Information

Date & Time: 03, Aug, 2026 20:11

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	97,830
Registration No.	CBT3471	Chassis No.	PA1B18F30P4201071
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.0	110	107	113
2	Boot Lid	113.3	117	104	119
3	Roof	98.3	101	99	93/101
4	Left Front Fender	106.3	103	108	108
5	Left Front Door	103.3	113	99	98
6	Center Panel Left				
7	Left Rear Door	99.9	100	100	100
8	Left Back Panel	97.3	97	95	100
9	Right Front Fender	107.3	106	109	107
10	Right Front Door	149.6	147	148	154
11	Center Panel Right				
12	Right Rear Door	100.4	103	102	96
13	Right Back Panel	108.0	102	107	115

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Minimal / Rear Seat - Grime - Medium / Mat Other - Missing - Yes / (R) Front Trim - Grime - Small / (R) Front Seat - Grime - Medium / (L) Front Trim - Grime - Small / (L) Front Floor Mat - Worked - Small / Carpet - Worked - Minimal / (L) Front Seat - Grime - Medium	Remarks (R) Front Fender, Molding - Scratch & Dent - Small / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Repair mark - Yes / (R) Front Door, Molding - Scratch & Dent - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Repair mark - Yes / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch & Dent - Large / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch & Dent - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Mirror - Crack - Damaged / Roof Spoiler, Molding - Dent - Minimal / Roof - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Crack, Gap - Large / Bonnet, Headlight - Scratch & Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes

With Lto plate, with spare tire and warranty booklet, 2keys, no tools and Jack, scratches on headlights and taillights,