

General Information

Date & Time: 03, Aug, 2026 19:23

Make	Toyota	Model	Fortuner
YOM	2022	Odo Meter Reading	59,334
Registration No.	CBD1453	Chassis No.	MHFAA8GSN0774936
CC	2.8	Transmission	A/T
Fuel Type	Diesel	Type of Body	SUV
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	118.6	104	124	128
2	Boot Lid	120.0	109	138	113
3	Roof	130.5	122	145	129/126
4	Left Front Fender	121.3	117	125	122
5	Left Front Door	115.3	122	112	112
6	Center Panel Left				
7	Left Rear Door	109.1	121	94	113
8	Left Back Panel	125.6	135	120	122
9	Right Front Fender	122.0	127	126	113
10	Right Front Door	119.0	119	114	124
11	Center Panel Right				
12	Right Rear Door	111.0	102	112	119
13	Right Back Panel	128.6	129	119	138

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A		Exterior Evaluation : D	
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain		A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap	
Remarks Ceiling - Grime - Small / Mat Other - Grime - Minimal / (R) Front Floor Mat - Grime - Minimal / (R) Front Seat - Grime - Minimal / (L) Front Floor Mat - Worked - Small / Carpet - Worked - Minimal / (L) Front Seat - Cut, Crack - Minimal		Remarks (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / Roof - Scratch & Dent - Minimal / Bonnet, Headlight - Scratch & Dent - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium	
Frame Evaluation : A		Functional Evaluation : A	
Remarks Defects not found		Remarks Spare Key - Issue - Unexist	

Inspector Notes

With Lto plate, with spare tire and jack, with warranty booklet, 1key, no tools, scratches on headlights, plate light issue, Worn front tires