

General Information

Date & Time: 03, Mar, 2025 16:32

Make	Toyota	Model	Vios
YOM	2024	Mileage	10,971
Registration No.	NHE8092	Chassis No.	PA1B18F30P4231879
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	111.3	102	98	134
2	Boot Lid	144.6	137	142	155
3	Roof	98.3	97	95	91/111
4	Left Front Fender	177.6	215	185	133
5	Left Front Door	137.6	138	136	139
6	Center Panel Left				
7	Left Rear Door	97.2	99	98	95
8	Left Back Panel	111.3	115	115	104
9	Right Front Fender	131.9	98	130	168
10	Right Front Door	97.0	98	95	99
11	Center Panel Right				
12	Right Rear Door	105.5	115	98	104
13	Right Back Panel	105.8	99	100	119

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Medium / Dashboard - Traces of Adhesive Tape - Yes / (L) Front Trim - Grime - Minimal / (R) Front Trim - Grime - Small / Ceiling - Grime - Minimal	Remarks (L) Front Fender - Repair Traces - Yes / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Rear Door, Molding - Dent - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes
no warranty booklet, no jack, incomplete tools, with spare tire, with LTO plate, park light issue, no reverse camera, member bolt missing