

General Information

Date & Time: 04, Mar, 2025 13:39

Make	Toyota	Model	Vios
YOM	2024	Mileage	13,772
Registration No.	NKB7758	Chassis No.	PA1B18F3R4250439
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	112.6	117	109	112
2	Boot Lid	108.6	107	109	110
3	Roof	117.0	121	107	127/113
4	Left Front Fender	102.3	103	101	103
5	Left Front Door	96.0	97	92	99
6	Center Panel Left				
7	Left Rear Door	111.3	105	109	120
8	Left Back Panel	113.3	118	115	107
9	Right Front Fender	106.6	103	109	108
10	Right Front Door	105.0	109	103	103
11	Center Panel Right				
12	Right Rear Door	120.6	112	121	129
13	Right Back Panel	115.0	110	119	116

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Large / (R) Front Seat - Grime - Medium / (L) Front Floor Mat - Worked - Small / (L) Front Trim - Grime - Minimal	Remarks (R) Front Door, Molding - Scratch - Large / Rear Bumper, Lamps, Panels - Scratch - Large / Trunk Hood, Rear Gate - Dent - Small / (R) Front Fender, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes

with warranty booklet, with jack and tools, with spare tire, with LTO plate
