


General Information

Date & Time: 04, Mar, 2025 10:32

Make	Toyota	Model	Veloz
YOM	2023	Mileage	18,458
Registration No.	BAF3667	Chassis No.	MHFAB1BY6N3045591
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	Wagon
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	116.6	120	112	118
2	Boot Lid	104.2	99	122	91
3	Roof	117.0	124	128	106/110
4	Left Front Fender	115.6	110	121	116
5	Left Front Door	118.0	115	109	130
6	Center Panel Left				
7	Left Rear Door	113.3	119	110	111
8	Left Back Panel	125.3	135	129	112
9	Right Front Fender	111.6	118	111	106
10	Right Front Door	114.0	117	111	114
11	Center Panel Right				
12	Right Rear Door	115.6	115	110	122
13	Right Back Panel	124.0	113	114	145

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Overall Interior - Animal Hair - Yes / Steering Wheel - Worn, Peel, Crack - Small	Remarks Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Dent - Small / Trunk Hood, Rear Gate - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / Roof - Dent - Small / (L) Rear Fender, Molding - Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
with warranty booklet and LTO plate/ with jack and spare tire / no tools