


General Information

Date & Time: 04, Mar, 2025 13:04

Make	Toyota	Model	Vios
YOM	2024	Mileage	15,017
Registration No.	BAF9068	Chassis No.	PA1B18F37R4241960
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	116.3	119	114	116
2	Boot Lid	104.4	105	97	111
3	Roof	113.0	121	113	108/110
4	Left Front Fender	106.3	102	110	107
5	Left Front Door	103.6	99	107	105
6	Center Panel Left				
7	Left Rear Door	107.3	100	104	118
8	Left Back Panel	112.6	117	112	109
9	Right Front Fender	104.6	106	102	106
10	Right Front Door	111.3	125	106	103
11	Center Panel Right				
12	Right Rear Door	100.5	97	98	107
13	Right Back Panel	104.2	99	107	107

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Mat Other - Grime - Medium / Rear Seat - Grime - Large / (R) Front Floor Mat - Grime - Medium / (R) Front Seat - Grime - Large / (L) Front Seat - Grime - Medium	Remarks (R) Front Fender, Molding - Repair mark - Yes / (R) Front Door, Molding - Repair mark - Yes / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with warranty booklet, with jack, incomplete tools, with spare tire, no LTO plate