

General Information

Date & Time: 05, Mar, 2025 09:26

Make	Toyota	Model	Vios
YOM	2024	Mileage	11,822
Registration No.	DBO4678	Chassis No.	PA1B18F35P4235099
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	103.3	109	100	101
2	Boot Lid	102.9	119	92	98
3	Roof	102.1	95	104	93/117
4	Left Front Fender	96.3	99	89	101
5	Left Front Door	94.1	97	91	95
6	Center Panel Left				
7	Left Rear Door	96.6	103	97	90
8	Left Back Panel	102.1	111	104	92
9	Right Front Fender	100.8	105	96	101
10	Right Front Door	101.5	111	95	99
11	Center Panel Right				
12	Right Rear Door	110.3	100	114	117
13	Right Back Panel	101.8	96	95	115

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Large / Rear Seat - Grime - Medium	Remarks (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Dent - Small / (L) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Front Door, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes

with LTO plate/with spare tire/with jack and tools/without warranty booklet/No reverse camera