


General Information

Date & Time: 20, Sep, 2024 10:45

Make	Toyota	Model	Rush
YOM	2023	Mileage	43,746
Registration No.	NGC7212	Chassis No.	MHKE8FF3PPK056739
CC	1.5	Transmission	A/T
Fuel Type	Gas	Type of Body	SUV
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.0	112	106	103
2	Boot Lid	112.6	106	124	108
3	Roof	108.4	94	112	112/116
4	Left Front Fender	114.0	120	111	111
5	Left Front Door	111.0	105	103	125
6	Center Panel Left				
7	Left Rear Door	121.6	126	107	132
8	Left Back Panel	119.6	144	117	98
9	Right Front Fender	126.6	123	105	152
10	Right Front Door	129.0	151	125	111
11	Center Panel Right				
12	Right Rear Door	123.3	128	123	119
13	Right Back Panel	110.3	105	103	123

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Trunk Room - Worn, Scratch, Cut, Crack - Medium	Remarks (R) Rear Fender, Molding - Scratch & Dent - Large / (L) Rear Door, Molding - Dent - Minimal / (L) Mirror - Scratch, Peeled - Yes / Bonnet, Headlight - Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes