

General Information

Date & Time: 21, Apr, 2025 17:30

Make	Toyota	Model	Avanza
YOM	2023	Mileage	26,472
Registration No.	CBK8595	Chassis No.	MHFAA1BY9N0010578
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	MPV
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	98.3	100	96	99
2	Boot Lid	77.9	79	72	82
3	Roof	99.4	117	108	84/89
4	Left Front Fender	89.8	90	91	88
5	Left Front Door	100.1	110	87	103
6	Center Panel Left				
7	Left Rear Door	97.1	104	91	97
8	Left Back Panel	102.1	100	94	112
9	Right Front Fender	90.7	95	86	92
10	Right Front Door	96.2	101	90	98
11	Center Panel Right				
12	Right Rear Door	99.3	102	91	105
13	Right Back Panel	106.1	117	95	106

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Minimal	Remarks Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Front Fender, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
with warranty booklet, with jack and tools, with spare tire, with LTO plate, windshield washer clogged