

General Information

Date & Time: 10, Mar, 2025 17:10

Make	Toyota	Model	Vios
YOM	2022	Mileage	129,296
Registration No.	NER8253 - NO ORCR	Chassis No.	-
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	99.9	110	80	110
2	Boot Lid	99.1	98	101	98
3	Roof	95.3	92	94	94/102
4	Left Front Fender	97.6	95	100	99
5	Left Front Door	96.6	101	91	98
6	Center Panel Left				
7	Left Rear Door	103.2	102	108	100
8	Left Back Panel	102.6	106	100	102
9	Right Front Fender	98.4	99	102	95
10	Right Front Door	182.0	305	127	114
11	Center Panel Right				
12	Right Rear Door	100.8	99	102	102
13	Right Back Panel	98.2	94	96	105

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : E
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain Remarks (R) Front Seat - Grime - Medium / (L) Front Seat - Grime - Medium / (R) Front Trim - Grime - Small / (R) Front Trim - Worked - Small / (L) Front Trim - Grime - Minimal / (L) Front Trim - Worked - Small / Dashboard - Traces of Adhesive Tape - Yes / Sunvisor, Sunglass Holder - Grime - Small / Ceiling - Grime - Small / Overall Interior - Smell - Yes / (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap Remarks (R) Front Door - Repair Traces - Yes / (R) Front Fender, Molding - Scratch & Dent - Medium / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Dent - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Dent - Medium / (L) Rear Fender, Molding - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch & Dent - Medium / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch & Dent - Large / Front Bumper, Grille, Lamps - Scratch - Large / Roof - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes

no warranty booklet, with jack and incomplete tools, with spare tire, with LTO plate, plate light issue