


General Information

Date & Time: 28, Mar, 2025 10:19

Make	Toyota	Model	Vios
YOM	2024	Mileage	10,628
Registration No.	CCA8796	Chassis No.	PA1B18F36R4257079
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	112.3	116	112	109
2	Boot Lid	108.6	106	109	111
3	Roof	105.9	102	100	115/107
4	Left Front Fender	94.0	98	90	94
5	Left Front Door	112.3	104	126	107
6	Center Panel Left				
7	Left Rear Door	113.6	119	112	110
8	Left Back Panel	105.5	105	114	98
9	Right Front Fender	102.1	98	105	103
10	Right Front Door	111.3	100	121	113
11	Center Panel Right				
12	Right Rear Door	103.6	100	100	111
13	Right Back Panel	112.3	105	107	125

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : A
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks (R) Front Seat - Grime - Medium	Remarks Front Bumper, Grille, Lamps - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist

Inspector Notes
with warranty booklet, with jack, incomplete tools, with spare tire, with LTO plate, weak battery