

General Information

Date & Time: 01, Apr, 2025 15:57

Make	Toyota	Model	Avanza
YOM	2024	Mileage	54,404
Registration No.	NHR6817	Chassis No.	MHFAA1BY7P0020075
CC	1.3	Transmission	M/T
Fuel Type	Gas	Type of Body	MPV
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	112.6	110	111	117
2	Boot Lid	99.7	105	106	88
3	Roof	123.5	137	131	117/109
4	Left Front Fender	103.0	100	101	108
5	Left Front Door	119.6	114	118	127
6	Center Panel Left				
7	Left Rear Door	114.0	115	115	112
8	Left Back Panel	108.0	113	111	100
9	Right Front Fender	106.2	114	107	98
10	Right Front Door	115.3	120	114	112
11	Center Panel Right				
12	Right Rear Door	113.0	122	109	108
13	Right Back Panel	111.0	107	104	122

Overall Evaluation :

D

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Floor Mat - Grime - Medium / (R) Front Seat - Grime - Medium / Rear Seat - Grime - Large / Trunk Room - Worked - Large / (L) Front Floor Mat - Worked - Large / Overall Interior - Smell - Yes	Remarks (L) Rear Door, Molding - Scratch & Dent - Large / (L) Front Door, Molding - Scratch - Medium / Trunk Hood, Rear Gate - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch - Large / (R) Rear Fender, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Large / (R) Front Fender, Molding - Scratch - Large / (L) Front Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Minimal / (L) Mirror - Scratch, Peeled - Minimal / (R) Mirror - Scratch, Peeled - Minimal / Roof - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : D
Remarks Defects not found	Remarks Warning Lamps - Issue - Yes / Shift Shock - Function - Weak / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes

with warranty booklet/ with jack and spare tire/ possible flooding/ with LTO PLATE/