

General Information

Date & Time: 28, Mar, 2025 07:55

Make	Toyota	Model	Vios
YOM	2024	Mileage	25,885
Registration No.	NHR3426	Chassis No.	PA1B18F38P4230172
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	111.0	109	103	121
2	Boot Lid	107.6	97	109	117
3	Roof	100.0	95	110	97/99
4	Left Front Fender	96.8	98	93	100
5	Left Front Door	102.6	100	106	102
6	Center Panel Left				
7	Left Rear Door	94.9	103	92	89
8	Left Back Panel	107.6	109	104	110
9	Right Front Fender	98.9	101	98	98
10	Right Front Door	107.3	116	103	103
11	Center Panel Right				
12	Right Rear Door	107.4	101	126	95
13	Right Back Panel	104.8	101	97	117

Overall Evaluation :

D

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Worked - Large / (R) Front Seat - Grime - Medium / Glove Box - Worn, Scratch, Cut, Crack - Medium / Rear Seat - Grime - Small</p>	<p>Remarks (L) Front Door, Molding - Scratch - Large / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (L) Front Fender, Molding - Scratch & Dent - Small / Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Front Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Large / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Medium</p>
Frame Evaluation : A	Functional Evaluation : C
<p>Remarks Defects not found</p>	<p>Remarks Power Steering - Issue - Yes / Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with warranty booklet and LTO plate, Jack, Spare tire and incomplete tools. crack and scratches on tail lights</p>