

General Information

Date & Time: 31, Mar, 2025 10:02

Make	Toyota	Model	Vios
YOM	2024	Mileage	17,770
Registration No.	DBO7559	Chassis No.	PA1B18F30R4257269
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	105.3	103	104	109
2	Boot Lid	104.6	103	103	108
3	Roof	100.6	110	97	96/100
4	Left Front Fender	95.1	96	93	96
5	Left Front Door	100.2	98	100	103
6	Center Panel Left				
7	Left Rear Door	101.6	104	105	96
8	Left Back Panel	101.2	105	102	97
9	Right Front Fender	96.4	99	95	95
10	Right Front Door	96.3	95	95	99
11	Center Panel Right				
12	Right Rear Door	104.4	95	103	115
13	Right Back Panel	103.5	92	96	123

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks (R) Front Seat - Grime - Small	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes

Inspector Notes
with warranty booklet, with jack and tools, with spare tire, no LTO plate