

General Information

Date & Time: 31, Mar, 2025 08:30

Make	Toyota	Model	Vios
YOM	2024	Mileage	14,855
Registration No.	NHS4002	Chassis No.	PA1B18F35R4259342
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition




#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	160.0	169	150	161
2	Boot Lid	178.0	183	165	186
3	Roof	95.8	106	93	84/100
4	Left Front Fender	98.8	101	92	103
5	Left Front Door	105.9	99	103	116
6	Center Panel Left				
7	Left Rear Door	130.3	137	125	129
8	Left Back Panel	103.8	111	101	99
9	Right Front Fender	137.6	142	131	140
10	Right Front Door	142.6	151	142	135
11	Center Panel Right				
12	Right Rear Door	147.6	140	144	159
13	Right Back Panel	102.8	96	102	111

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : C
<div style="text-align: center; background-color: #cccccc; padding: 50px;">  <p>No Image</p> </div> <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<div style="text-align: center;">  </div> <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Worked - Large / (R) Front Seat - Grime - Medium</p>	<p>Remarks (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair mark - Yes / Bonnet, Headlight - Repair mark - Yes / (L) Front Fender, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch - Small / (L) Rear Fender, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / Roof - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Medium</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>With warranty booklet and tools, spare tire and jack. No LTO PLATE, adhesive mark on both rear door. have scratches on tail lights.</p>