


General Information

Date & Time: 04, Apr, 2025 14:33

Make	Toyota	Model	Veloz
YOM	2024	Mileage	42,022
Registration No.	DBM2331	Chassis No.	MHFAB1BY4P3082190
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	SUV
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	98.3	95	96	104
2	Boot Lid	120.0	127	112	121
3	Roof	114.2	123	129	104/101
4	Left Front Fender	95.0	96	97	93
5	Left Front Door	102.5	104	97	107
6	Center Panel Left				
7	Left Rear Door	106.6	107	106	107
8	Left Back Panel	99.6	96	100	103
9	Right Front Fender	94.6	90	96	97
10	Right Front Door	103.1	109	102	98
11	Center Panel Right				
12	Right Rear Door	101.5	103	98	104
13	Right Back Panel	92.1	83	99	94

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes
with warranty booklet, with jack and tools, with spare tire, with LTO plate, dome light issue