


General Information

Date & Time: 22, Apr, 2025 14:42

Make	Toyota	Model	Vios
YOM	2024	Mileage	8,165
Registration No.	BAG6611	Chassis No.	PA1B18F30R4276386
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.8	115	98	110
2	Boot Lid	98.5	96	100	100
3	Roof	90.0	90	93	87/90
4	Left Front Fender	92.5	96	94	88
5	Left Front Door	91.3	88	89	97
6	Center Panel Left				
7	Left Rear Door	94.5	102	92	90
8	Left Back Panel	98.9	105	104	88
9	Right Front Fender	94.7	92	91	101
10	Right Front Door	102.6	109	99	100
11	Center Panel Right				
12	Right Rear Door	97.7	93	90	110
13	Right Back Panel	98.1	97	93	104

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Large / (L) Front Trim - Grime - Minimal / (L) Front Seat - Grime - Small / Ceiling - Grime - Minimal / (R) Front Seat - Grime - Large	Remarks (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch & Dent - Large / (L) Front Door, Molding - Scratch - Large / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Bonnet, Headlight - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

no LTO plate, with warranty booklet, with jack, no tools, no spare tire