

General Information

Date & Time: 14, Apr, 2025 10:05

Make	Toyota	Model	Vios
YOM	2025	Mileage	6,292
Registration No.	DBQ1436	Chassis No.	PA1B18F36R4265652
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	120.6	123	119	120
2	Boot Lid	116.0	106	123	119
3	Roof	113.0	116	120	103/113
4	Left Front Fender	107.6	111	103	109
5	Left Front Door	106.6	103	110	107
6	Center Panel Left				
7	Left Rear Door	111.3	123	107	104
8	Left Back Panel	109.0	116	108	103
9	Right Front Fender	117.3	123	114	115
10	Right Front Door	112.0	105	116	115
11	Center Panel Right				
12	Right Rear Door	115.3	124	106	116
13	Right Back Panel	124.3	120	121	132

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Trim - Grime - Minimal / Dashboard - Traces of Adhesive Tape - Yes / Rear Seat - Grime - Minimal / (L) Front Floor Mat - Grime - Minimal / (L) Front Trim - Grime - Medium / Ceiling - Grime - Small	Remarks Trunk Hood, Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with LTO plate/with spare tire/with warranty booklet/No jack and tools